



# Technical Bulletin 274

Version 1.0 13/12/2024

## Panther Firmware Version Update V1.50

This technical bulletin provides awareness of a new firmware update relating to Panther leak detector from ION Science, introducing a key bug fix.

### Details of the Panther Firmware update V1.50

1. **Intermittent firmware freeze bug fix:** We have introduced a fix for an intermittent bug causing firmware to freeze during start-up. The firmware now runs through the start-up routine smoothly.

This update enhances the usability of the Panther Leak Detector, providing a more reliable and efficient experience for users.

Please install the new firmware to ensure you are up to date.

Internal reference: IO-003722-CN

E: [info@ionscience.com](mailto:info@ionscience.com)

T: +44 (0)1763 208 503

Pioneering Gas Sensing Technology.  
[ionscience.com](http://ionscience.com)