



# IECEx Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **GB/BAS/QAR07.0023/11**

Page 1 of 2

QAR Free Ref. No.: **2242**

Status: **Issued**

Details of change: **Special Assessment**

Date of issue: **2024-06-13**

Location(s) audited: **Ion Science Limited**  
The Hive  
Butts Lane  
Fowlmere  
Royston  
SG8 7SL  
United Kingdom

Valid until: **2027-06-06**

Audit date: **2024-06-06**

Issuing ExCB: **SGS - SGS United Kingdom Ltd**

Manufacturer: **Ion Science Limited**  
The Hive  
Butts Lane  
Fowlmere  
Royston  
SG8 7SL

Location of  
Manufacturer: **United Kingdom**

Product information: **Gas detection and measurement equipment**

Type of protection: **Ex i, d, op, op is (Note : Concept d is included as a result of the use of a pre certified component. The Manufacturer has not been assessed for manufacture in relation to that concept.)**

Related QARs:

[GB/BAS/QAR07.0023/00](#)  
[GB/BAS/QAR07.0023/03](#)  
[GB/BAS/QAR07.0023/06](#)  
[GB/BAS/QAR07.0023/09](#)

[GB/BAS/QAR07.0023/01](#)  
[GB/BAS/QAR07.0023/04](#)  
[GB/BAS/QAR07.0023/07](#)  
[GB/BAS/QAR07.0023/10](#)

[GB/BAS/QAR07.0023/02](#)  
[GB/BAS/QAR07.0023/05](#)  
[GB/BAS/QAR07.0023/08](#)

Related Certificates (manual insertion)::

**IECEx BAS 04.0033**

Related Certificates (automatic linking)::

IECEx BAS 07.0030U issue: 13  
IECEx FTZU 16.0011X issue: 2

IECEx BAS 11.0014 issue: 11  
IECEx KSCP 24.0047X issue: 0

IECEx SGS 25.0002X issue: 0

Related Certificates for  
previous versions:

IECEx BAS 06.0057 issue: 2  
IECEx BAS 06.0057X issue: 5  
IECEx BAS 07.0030U issue: 1  
IECEx BAS 07.0030U issue: 4  
IECEx BAS 07.0030U issue: 7  
IECEx BAS 07.0030U issue: 10  
IECEx BAS 11.0014 issue: 0  
IECEx BAS 11.0014 issue: 3  
IECEx BAS 11.0014 issue: 6  
IECEx BAS 11.0014 issue: 9  
IECEx BAS 19.0049X issue: 1  
IECEx CML 20.0007 issue: 1  
IECEx FTZU 14.0030X issue: 2  
IECEx ITS 10.0036X issue: 0  
IECEx ITS 10.0036X issue: 4

IECEx BAS 06.0057 issue: 3  
IECEx BAS 06.0065U issue: 2  
IECEx BAS 07.0030U issue: 2  
IECEx BAS 07.0030U issue: 5  
IECEx BAS 07.0030U issue: 8  
IECEx BAS 07.0030U issue: 11  
IECEx BAS 11.0014 issue: 1  
IECEx BAS 11.0014 issue: 4  
IECEx BAS 11.0014 issue: 7  
IECEx BAS 11.0014 issue: 10  
IECEx BAS 19.0049X issue: 2  
IECEx FTZU 14.0030X issue: 0  
IECEx FTZU 16.0011X issue: 0  
IECEx ITS 10.0036X issue: 1  
IECEx ITS 10.0036X issue: 5

IECEx BAS 06.0057X issue: 4  
IECEx BAS 07.0030U issue: 0  
IECEx BAS 07.0030U issue: 3  
IECEx BAS 07.0030U issue: 6  
IECEx BAS 07.0030U issue: 9  
IECEx BAS 07.0030U issue: 12  
IECEx BAS 11.0014 issue: 2  
IECEx BAS 11.0014 issue: 5  
IECEx BAS 11.0014 issue: 8  
IECEx BAS 19.0049X issue: 0  
IECEx CML 20.0007 issue: 0  
IECEx FTZU 14.0030X issue: 1  
IECEx FTZU 16.0011X issue: 1  
IECEx ITS 10.0036X issue: 3  
IECEx ITS 10.0036X issue: 6

-- Continued on the next page



# IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/BAS/QAR07.0023/11**

Page 2 of 2

Related Certificates for  
previous versions (continued):

IECEx ITS 10.0036X issue: 7  
IECEx ITS 10.0036X issue: 10

IECEx ITS 10.0036X issue: 8  
IECEx ITS 22.0025X issue: 0

IECEx ITS 10.0036X issue: 9

Comments: See BAS/QAR 06.0035 for previous details